

Created: 2004-10-05

Autodiagnos Technical Bulletin

SYSTEM: VW Golf / Jetta all models

TITLE: Erratic instrument cluster functions

ISSUE: Wiring Failure

Erratic instrument cluster functions, MIL on, Lambda fault codes present. Bad earth connection under the battery tray in the engine compartment. Battery will have to be removed to access the fixing studs.

The information in this data sheet is subject to change without notice. Autodiagnos shall not be liable for technical or editorial errors or omissions contained herein; nor for incidental or consequential damages resulting from the furnishing, performance, or use of this material.
