

Created: 2004-10-05

## **Autodiagnos Technical Bulletin**

**SYSTEM:** 1.8T Engines with AGU code

**TITLE:** Fault codes for Hall sensor, Map Sensor, & Idle Adaption

**ISSUE:** Loom Damage

Wiring chaffed through under battery tray, above gear change linkage, loss of 5V feed to the sensors.

-----  
The information in this data sheet is subject to change without notice. Autodiagnos shall not be liable for technical or editorial errors or omissions contained herein; nor for incidental or consequential damages resulting from the furnishing, performance, or use of this material.  
-----