

Created: 2004-10-05

## **Autodiagnos Technical Bulletin**

**SYSTEM:** TD5 MY 1999

**TITLE:** Engine ECU

**ISSUE:** Module Damage

Engine oil penetrates the injector wiring loom, and osmisises back to the Engine ECU, effectively destroying it. Replace loom & ECU, but there is no mod available to prevent reoccurrence.

---

The information in this data sheet is subject to change without notice. Autodiagnos shall not be liable for technical or editorial errors or omissions contained herein; nor for incidental or consequential damages resulting from the furnishing, performance, or use of this material.

---