

Created: 2003-xx-xx

Autodiagnos Technical Bulletin

SYSTEM: BMW

TITLE: AIRBAG COMMUNICATION

ISSUE:

E36 with airbag warning light in steering wheel.

BACKGROUND:

This is a retrofit complete unit, so there is no connection to the diagnostic socket and no diagnosable parts in this system. That is why you cannot communicate using any diagnostic tool, including the Multi-Tester pro.

The information in this data sheet is subject to change without notice. Autodiagnos shall not be liable for technical or editorial errors or omissions contained herein; nor for incidental or consequential damages resulting from the furnishing, performance, or use of this material.
