

DOC.ID: TBE000619-05

Diagnostic advice

TITLE: Volvo Serial

ISSUE: No communication with instrument cluster "Combi"

BACKGROUND: Volvo cars have different brands of instrument clusters VDO, Yasaki etc. Note that the Yasaki instrument clusters do not have any self-diagnostics implemented.

ACTION: The following can identify the Yasaki instrument clusters:

1. Rpm scale to 8000rpm (VDO-7000rpm)
2. Trip reset button right side of speedometer (VDO left side)
3. Numbers on the speedometer and rpm are placed inside the grading lines (VDO outside).

NOTES: A manual reset is necessary on the service light on a Yasaki, by pushing the reset button.

The information in this data sheet is subject to change without notice. Autodiagnos AB shall not be liable for technical or editorial errors or omissions contained herein; nor for incidental or consequential damages resulting from the furnishing, performance, or use of this material.
